




TOP VIEW OF LID

NO SCALE




TOP VIEW OF BOX

NO SCALE




END VIEW OF BOX

NO SCALE




SECTION - LID FRAME



CUTTING DIAGRAMS FOR 24 GA. GALVANIZED STEEL PANS


NO SCALE



SIDE VIEW, COMPLETE UNIT

NOTES

1. PAINT INSIDE WHITE.
2. PAINT OUTSIDE BLACK.
3. SEAL ALL CRACKS.
4. PLACE IN PROTECTED PLACE ON SOUTH SIDE OF A BUILDING.
5. REMOVE WAX AND HONEY WHEN MOST COMBS ARE MELTED. THE HONEY SHOULD BE DISCARDED.



NO SCALE

BASED ON: PENN STATE UNIV.
PLAN NO. 790-301

COOPERATIVE EXTENSION WORK IN
AGRICULTURE AND HOME ECONOMICS
STATE OF TENNESSEE
UNIVERSITY OF TENNESSEE
AND
UNITED STATES DEPARTMENT OF AGRICULTURE COOPERATING

SOLAR BEESWAX EXTRACTOR

PA '77 6265 SHEET 1 OF 1